



Colliers charnières PPFV

Collier de réparation

ITEM 141

RÉFÉRENCE	DESCRIPTION	Poids net	Volume (m³)	Poids brut	Unités par lot
1005050	CORPS COLLIER REPARATION 225	2,67	0,04460	3,331	2
1005051	CORPS COLLIER REPARATION 250	3,635	0,04836	7,94	2
1005052	CORP COLLIER REPARATEUR 315	6,8197	0,04880	7,395	1
1005053	CORPS COLLIER REPARATION 200	2,484	0,04460	5,798	2
1005054	CORPS COLLIER REPARATION 400	6,125	0,06347	6,925	1
1005055	CORPS COLLIER REPARATION 160	3,11325	0,03648	6,98	2



Pol. Ind. Plá Vallonga,
c/ Agua, 28
03006 ALICANTE (España)



+34 965 11 42 82



+34 965 11 48 62




tecnicocomercial@hidroten.es



Service d'Attention
Technique Commerciale
+34 966 105 888



www.hidroten.es



ITEM 141 | Collier de réparation

CÓDIGO	f tubo	PESOS	A	B	C	PN	MEDIDA
05055	160	2535	160	225	186	PN6	MÉTRICO
05053	200	2484	200	227	226	PN6	MÉTRICO
05050	225	2717	225	225	250	PN6	MÉTRICO
05051	250	3096	250	239	276	PN6	MÉTRICO
05052	315	4398	315	250	344	PN6	MÉTRICO
05054	400	6125	400	282	430	PN6	MÉTRICO





Documentation Produit



Certifications de produits

Certificats d'entreprise



Pol. Ind. Plá Vallonga,
c/ Agua, 28
03006 ALICANTE (España)



+34 965 11 42 82



+34 965 11 48 62



tecnicocomercial@hidroten.es



Service d'Attention
Technique Commerciale
+34 966 105 888



www.hidroten.es